

2.008 Design & Manufacturing II

Spring 2004

Metal Cutting I

2.008-spring-2004
S.Kim

1


Today, February 25th

- HW#2 due before the class, #3 out on the web after the class.
 - Math Formulae, handout
- Lab groups fixed, and thank you.
 - group report!!!
- Metal cutting demo
- Cutting physics

2.008-spring-2004 S.Kim

2

A lathe of pre WWII



2.008-spring-2004 S.Kim

3

Material removal processes


- Cost:
 - Expensive \$100 - \$10,000
- Quality:
 - Very high
- Flexibility:
 - Any shape under the sun
- Rate:
 - Slow



2.008-spring-2004 S.Kim

4


Surface roughness by machining



2.008-spring-2004 S.Kim

5

Machined Surface



- Rough 1000
- Medium 500
- Avg. Better than Avg. 125
- Fine 63
- Very fine 32
- Extremely fine 16
- 8

2.008-spring-2004 S.Kim

6


Cutting processes

- Why do we study cutting physics?
 - Product quality: surface, tolerance
 - Productivity: MRR↑, Tool wear↓
- Physics of cutting
 - Mechanics
 - Force, power
- Tool materials
- Design for manufacturing

2.008-spring-2004 S.Kim

7

Cutting Tools



2.008-spring-2004 S.Kim

8


Cutting process modeling

- Methods: Modeling and Experiments
- Key issues
 - How does cutting work?
 - What are the forces involved?
 - What affect does material properties have?
 - How do the above relate to power requirements, MRR, wear, surface?

2.008-spring-2004 S.Kim

9


Orthogonal cutting in a lathe



2.008-spring-2004 S.Kim

10


Cutting tool and workpiece..



2.008-spring-2004 S.Kim

11

Varying rake angle α :




2.008-spring-2004 S.Kim

12

Basic cutting geometry

- We will use the orthogonal model



Continuity

$$V \cdot t_0 = V_c \cdot t_c$$

t_c : chip thickness
 t_0 : depth of cut


Cutting ratio: $r < 1$

$$\frac{V_c}{V} = \frac{t_0}{t_c} = r = \frac{\sin(\phi)}{\cos(\phi - \alpha)}$$

2.008-spring-2004 S.Kim

13

Velocity diagram in cutting zone



Law of sines

$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos(\alpha)} = \frac{V_c}{\sin(\phi)}$$

$$\frac{V_c}{V} = \frac{t_0}{t_c} = r = \frac{\sin(\phi)}{\cos(\phi - \alpha)}$$

$$V_c = \frac{V \sin(\phi)}{\cos(\phi - \alpha)}$$


2.008-spr ng 2004 S.Kim

14

Forces and power

- FBD at the tool-workpiece contact
- What are the forces involved


- Thrust force, F_t
- Cutting force, F_c
- Resultant force, R
- Friction force, F
- Normal Force, N
- Shear Force, F_s, F_n



2.008-spring-2004 S.Kim

15

E. Merchant's cutting diagram



Source: Kalpakjian

2.008-spring-2004 S.Kim

16

FBD of Forces

$$F = R \cdot \sin(\beta) \quad \beta = \text{Friction Angle} \quad F_t = R \cdot \sin(\beta - \alpha)$$

$$N = R \cdot \cos(\beta) \quad \mu = \tan(\beta) \quad F_c = R \cdot \cos(\beta - \alpha)$$

$$F_s = F_c \cdot \cos(\phi) - F_t \cdot \sin(\phi) = R \cos(\phi + \beta - \alpha)$$

$$F_n = F_c \cdot \sin(\phi) + F_t \cdot \cos(\phi)$$

$$\mu = \frac{F}{N} = \frac{F_t + F_c \cdot \tan(\alpha)}{F_c - F_t \cdot \tan(\alpha)}$$


Typically: $0.5 < \mu < 2$



2.008-spring-2004 S.Kim

17

Analysis of shear strain



$$\gamma = \frac{\Delta s}{l} = \frac{bc + cd}{ac} = \cot \phi + \tan(\phi - \alpha)$$

- What does this mean:
 - Low shear angle = large shear strain
 - Merchant's assumption: Shear angle adjusts to minimize cutting force or max. shear stress
- Can derive:

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2}$$

2.008-spring-2004 S.Kim

18

Shear angle

$$F_c = R \cdot \cos(\beta - \alpha)$$

$$F_s = F_c \cdot \cos(\phi) - F_f \cdot \sin(\phi) = R \cos(\phi + \beta - \alpha)$$

$$F_c = F_s \cos(\beta - \alpha) / \cos(\phi + \beta - \alpha)$$

$$F_s = A_s \cdot \sigma_s \text{ (area of shear plane, shear strength)}$$

$$F_c = \sigma_s \frac{A}{\sin \phi} \cos(\beta - \alpha) / \cos(\phi + \beta - \alpha)$$

$$dF_c/d\phi = 0 \longrightarrow \phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2}$$


2.008-spring-2004 S.Kim

19

Things to think about

- As rake angle decreases or friction increases
 - Shear angle decreases
 - Chip becomes thicker
 - Thicker chip = more energy dissipation via shear
 - More shear = more heat generation
 - Temperature increase!!!

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2}$$



2.008-spring-2004 S.Kim

20

Power

Power input: $F_c \cdot V$ => shearing + friction

Power for shearing: $F_s \cdot V_s$

Specific energy for shearing: $u_s = \frac{F_s \cdot V_s}{w \cdot t_o \cdot V}$

Power dissipated via friction: $F_f \cdot V_c$ ← MRR

Specific energy for friction: $u_f = \frac{F_f \cdot V_c}{w \cdot t_o \cdot V}$

Total specific energy: $u_s + u_f = \frac{F_s \cdot V_s}{w \cdot t_o \cdot V} + \frac{F_f \cdot V_c}{w \cdot t_o \cdot V}$

Experimental data

2.008-spring-2004 S.Kim

21

Specific energy (rough estimate)

Approximate Energy Requirements in Cutting Operations (at drive motor, corrected for 80% efficiency; multiply by 1.25 for dull tools).


Material	Specific energy	
	W · s/mm ³	hp · min/in. ³
Aluminum alloys	0.4–1.1	0.15–0.4
Cast irons	1.6–5.5	0.6–2.0
Copper alloys	1.4–3.3	0.5–1.2
High-temperature alloys	3.3–8.5	1.2–3.1
Magnesium alloys	0.4–0.6	0.15–0.2
Nickel alloys	4.9–6.8	1.8–2.5
Refractory alloys	3.8–9.6	1.1–3.5
Stainless steels	3.0–5.2	1.1–1.9
Steels	2.7–9.3	1.0–3.4

2.008-spring-2004 S.Kim

Kalpalkjian

22

Example




- Consider the turning with a rod, from 1.25 inch diameter to 1.0.
- t_o : depth of cut, 0.005 inch
- f : feed rate, 0.025 inch/rev
- ω : spindle speed, 1000 rpm
- u_f : specific energy for friction
- u_s : specific energy for shear, 0.35 hp min/in³
- 1 hp = 550 ft.lbf/s
- How many passes?
- Tools speed?
- Time to make this part?
- V c max?
- Max power needed?
- Initial cutting force?

2.008-spring-2004 S.Kim

23

Cutting zone pictures



2.008-spring-2004 S.Kim

Kalpalkjian

24