


Brittle fracture: The S.S. Schenectady, after failing at the pier in calm weather in 1941.



MIT OpenCourseWare
<http://ocw.mit.edu>

3.11 Mechanics of Materials

Fall 1999

For information about citing these materials or our Terms of Use, visit: <http://ocw.mit.edu/terms>.